	Туре	Hits	Search Text		DBs
1	BRS	162084	(motor adj vehicle) or automobile	USPAT;	ŲS-PGPUB
2	BRS	328074	injecting or molding	USPAT;	US-PGPUB
3	BRS	5235	fascia	USPAT;	US-PGPUB
4	BRS	538	((motor adj vehicle) or automobile) and fascia	USPAT;	US-PGPUB
5	BRS	275	<pre>(injecting or molding) and (((motor adj vehicle) or automobile) and fascia)</pre>		US-PGPUB
6	BRS	5396	264/250,255,259,266,274,275.cc ls.	USPAT;	US-PGPUB
7	BRS	22262	(automotive or vehicle) with panel	USPAT;	US-PGPUB
8	BRS	61112	bumper or trim	USPAT;	US-PGPUB
9	BRS	4070	((automotive or vehicle) with panel) and (bumper or trim)	USPAT;	US-PGPUB
10	BRS	1372	<pre>(injecting or molding) and (((automotive or vehicle) with panel) and (bumper or trim))</pre>	USPAT;	US-PGPUB
11	BRS	2	<pre>fascia and (264/250,255,259,266,274,275.c cls. and ((injecting or molding) and (((automotive or vehicle) with panel) and (bumper or trim))))</pre>	USPAT;	US-PGPUB
12	BRS	9	((injecting or molding) and (((motor adj vehicle) or automobile) and fascia)) and 264/250,255,259,266,274,275.cc ls.	USPAT;	US-PGPUB
13	BRS	73	264/250,255,259,266,274,275.cc ls. and (((automotive or vehicle) with panel) and (bumper or trim))	USPAT;	US-PGPUB
14	BRS	2495	264/255,274.ccls.	USPAT;	US-PGPUB
15	BRS	36	(264/250,255,259,266,274,275.c cls. and (((automotive or vehicle) with panel) and (bumper or trim))) and 264/255,274.ccls.	USPAT;	US-PGPUB
16	BRS	37	(264/250,255,259,266,274,275.c cls. and (((automotive or vehicle) with panel) and (bumper or trim))) not ((264/250,255,259,266,274,275.ccls. and (((automotive or vehicle) with panel) and (bumper or trim))) and 264/255,274.ccls.)	USPAT;	US-PGPUB

08/25/2003, EAST Version: 1.04.0000

	Time Stamp	Comments	Error Definition	Errors
1	2003/08/22 16:57			0
2	2003/08/22 16:58			0
3	2003/08/22 16:59			0
4	2003/08/22 16:59			0
5	2003/08/22 17:01			0
6	2003/08/22 17:02			0
7	2003/08/22 17:03			0
8	2003/08/22 17:03			0
وا	2003/08/22 17:03			0
10	2003/08/22 17:04			0
11	2003/08/22 17:04			0
12	2003/08/22 17:05			0
13	2003/08/22 17:09			0
14	2003/08/22 17:09			0
15	2003/08/22 17:17			0
16	2003/08/22 17:18			0

08/25/2003, EAST Version: 1.04.0000

	Туре	Hits	Search Text	DBs
17	BRS	70	264/250,255,259,266,274,275.cc ls. and ((injecting or molding) and (((automotive or vehicle) with panel) and (bumper or trim)))	
18	BRS	0	(264/250,255,259,266,274,275.c cls. and ((injecting or molding) and (((automotive or vehicle) with panel) and (bumper or trim)))) not (264/250,255,259,266,274,275.c cls. and (((automotive or vehicle) with panel) and (bumper or trim)))	USPAT; US-PGPUB
19	BRS	0	grille and (264/250,255,259,266,274,275.c cls. and (((automotive or vehicle) with panel) and (bumper or trim)))	USPAT; US-PGPUB
20	BRS	0	grille and (264/250,255,259,266,274,275.c cls. and ((injecting or molding) and (((automotive or vehicle) with panel) and (bumper or trim))))	USPAT; US-PGPUB
21	BRS	3	grill and (264/250,255,259,266,274,275.c cls. and (((automotive or vehicle) with panel) and (bumper or trim)))	USPAT; US-PGPUB
22	BRS	3	grill and (264/250,255,259,266,274,275.c cls. and ((injecting or molding) and (((automotive or vehicle) with panel) and (bumper or trim))))	USPAT; US-PGPUB
23	BRS	22	grill and 264/250,255,259,266,274,275.cc ls.	USPAT; US-PGPUB

	Time Stamp	Comments	Error Definition	Errors
17	2003/08/22 17:24			0
18	2003/08/22 17:24			0
19	2003/08/22 17:24			0
20	2003/08/22 17:25			O
21	2003/08/22 17:25			0
22	2003/08/22 17:26			0
23	2003/08/22 17:27			0